Report No.: TRE1703026201 Page: 31 of 38 Issued: 2017-04-18








Report No.: TRE1703026201 Page: 32 of 38 Issued: 2017-04-18









Report No.: TRE1703026201 Page: 33 of 38 Issued: 2017-04-18


Internal photos









Report No.: TRE1703026201 Page: 34 of 38 Issued: 2017-04-18










Report No.: TRE1703026201 Page: 35 of 38 Issued: 2017-04-18










Report No.: TRE1703026201 Page: 36 of 38 Issued: 2017-04-18










Report No.: TRE1703026201 Page: 37 of 38 Issued: 2017-04-18









Report No.: TRE1703026201 Page: 38 of 38 Issued: 2017-04-18







.....End of Report.....