



172200_01: Test setup shielded room M4

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 1 of 11





172200_02: Test setup shielded room M4

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 2 of 11






172200_03: Test setup anechoic chamber M20, 9 kHz - 30 MHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 3 of 11





172200_04: Test setup anechoic chamber M20, 9 kHz - 30 MHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 4 of 11





172200_05: Test setup open area test site, 9 kHz - 30 MHz @ 3m

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 5 of 11





172200_06: Test setup open area test site, 9 kHz - 30 MHz @ 3m

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 6 of 11





172200_07: Test setup open area test site, 9 kHz - 30 MHz @ 10m

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 7 of 11






172200_08: Test setup open area test site, 9 kHz - 30 MHz @ 10m

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 8 of 11





172200_09: Test setup anechoic chamber M20, 30 MHz - 1 GHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200
 page 9 of 11






172200_10: Test setup open area test site M6, 30 MHz - 1 GHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200

 page 10 of 11
 page 10 of 11





172200_11: Test setup open area test site M6, 30 MHz - 1 GHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F172200E1

 Date of issue:
 23.07.2018
 Order Number:
 17-112200

 page 11 of 11
 page 11 of 11