


Date: 2018-12-11

Report Number: 60.790.18.050.01






Page 1 of 9
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-11

Report Number: 60.790.18.050.01








Date: 2018-12-11


Report Number: 60.790.18.050.01

Model No.: 75004PP03 FCC ID: 2AK9F-7500

BLE and ANT+ Antenna

2402-2480MHz








Date: 2018-12-11

Report Number: 60.790.18.050.01






Page 4 of 9 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong




Date: 2018-12-11

Report Number: 60.790.18.050.01

Model No.: 75004PP03 FCC ID: 2AK9F-7500






Page 5 of 9
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-11

Report Number: 60.790.18.050.01

Model No.: 75004PP03 FCC ID: 2AK9F-7500







Page 6 of 9 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-11

Report Number: 60.790.18.050.01







Page 7 of 9 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-11

Report Number: 60.790.18.050.01






Page 8 of 9 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-11

Report Number: 60.790.18.050.01





Page 9 of 9 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong