Test report No. : 12311666H-B-R1
Page : 13 of 15
Issued date : August 28, 2018
FCC ID : 2AKB8K52RA

APPENDIX 3: Photographs of test setup

Radiated Emission

(Below 1GHz)




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

 Test report No.
 : 12311666H-B-R1

 Page
 : 14 of 15

 Issued date
 : August 28, 2018

 FCC ID
 : 2AKB8K52RA

Radiated Emission

(Above 1GHz)




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12311666H-B-R1
Page : 15 of 15
Issued date : August 28, 2018
FCC ID : 2AKB8K52RA

Worst Case Position
(Horizontal: X-axis / Vertical: X-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124