Test report No. : 11370534H-A-R1

Page : 17 of 18

Issued date : January 27, 2017 FCC ID : 2AKB8HAR0001

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11370534H-A-R1 : 18 of 18 Page

: January 27, 2017 : 2AKB8HAR0001 **Issued date** FCC ID

Worst Case Position

BCM Below 30MHz X-axis **Above 30MHz** Horizontal:X-axis / Vertical:X-axis










<u>ANT</u> Below 30MHz X-axis Above 30MHz Horizontal:X-axis / Vertical:X-axis X-axis







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: +81 596 24 8999 Telephone : +81 596 24 8124 Facsimile