Test report No.
 : 12742873H-B-R1

 Page
 : 15 of 17

 Issued date
 : May 20, 2019

 FCC ID
 : 2AKB8HAR0004

### **APPENDIX 3: Photographs of test setup**

# Radiated Emission (Below 1 GHz)




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 12742873H-B-R1

 Page
 : 16 of 17

 Issued date
 : May 20, 2019

 FCC ID
 : 2AKB8HAR0004

## Radiated Emission (Above 1 GHz)




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12742873H-B-R1 : 17 of 17 Page : May 20, 2019 : 2AKB8HAR0004 **Issued date** FCC ID

<u>Worst Case Position</u> (Horizontal: X-axis / Vertical: X-axis)

#### X-axis



Y-axis



**End of Report** 

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124