Test report No. : 11370534H-B Page : 13 of 15

Issued date : December 1, 2016 FCC ID : 2AKB8HAR0001

APPENDIX 3: Photographs of test setup

Radiated Emission (Below 1GHz)




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11370534H-B : 14 of 15 Page

: December 1, 2016 : 2AKB8HAR0001 **Issued date** FCC ID

Radiated Emission (Above 1GHz)




Photo 1




Photo 2


UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11370534H-B Page : 15 of 15 Issued date : December 1, 2016

FCC ID : 2AKB8HAR0001

<u>Worst Case Position</u> (Horizontal: X-axis / Vertical: X-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124