Test report No. : 11581744H-B
Page : 13 of 15
Issued date : March 15, 2017
FCC ID : 2AKB8DA5501

APPENDIX 3: Photographs of test setup

Radiated Emission (Below 1GHz)



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11581744Н-В : 14 of 15 Page Issued date : March 15, 2017 : 2AKB8DA5501 FCC ID

Radiated Emission (Above 1GHz)



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11581744H-B
Page : 15 of 15
Issued date : March 15, 2017
FCC ID : 2AKB8DA5501

Worst Case Position

(Horizontal: Z-axis / Vertical: Z-axis) (Below 1 GHz) (Horizontal: X-axis / Vertical: X-axis) (Above 1 GHz)





Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124