


Inside view of EUT



Report no. ETLT161111.0129, Page D1 of D10



Top side view of main board




Report no. ETLT161111.0129, Page D2 of D10

Head Office: #371-51, Gasan-dong, Geumcheon-gu, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-0788 **Open site:** #499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, Korea




Bottom side view of main board



Report no. ETLT161111.0129, Page D3 of D10



Top side view of Sub board #1




Report no. ETLT161111.0129, Page D4 of D10

Head Office: #371-51, Gasan-dong, Geumcheon-gu, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-0788

Open site: #499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, Korea



Bottom side view of Sub board #1



Report no. ETLT161111.0129, Page D5 of D10

 $\textbf{Head Office:} \ \#371-51, \ Gasan-dong, \ Geumcheon-gu, \ Seoul, \ 153-803, \ Korea \qquad \textbf{Tel:} \ 82-2-858-0786 \qquad Fax: \ 82-2-858-0788$

Open site:#499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, KoreaETLQP-21-F40-0



Top side view of Sub board #2



Report no. ETLT161111.0129, Page D6 of D10

Head Office: #371-51, Gasan-dong, Geumcheon-gu, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-0788 **Open site:** #499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, Korea



Bottom side view of Sub board #2




Report no. ETLT161111.0129, Page D7 of D10



View of Rechargeable Li-ion battery





Report no. ETLT161111.0129, Page D8 of D10



View of LDS antenna





Inside View of Cradle (for Battery charger)

