

Appendix D. Setup Photographs

<Radiated Emission>

X Plane

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AKJ5-N2 Page Number : D1 of D2
Report Issued Date : May 03, 2017
Report Version : Rev. 01

Report No.: FR6D2204C

Report Template No.: BU5-FR15CWL Version 2.0



Report No.: FR6D2204C

Y Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AKJ5-N2 Page Number : D2 of D2
Report Issued Date : May 03, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 2.0