Appendix C. Setup Photographs

<Radiated Emission> Y plane for Part 27H

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AKJ5-N2 Page Number : C1 of C3
Report Issued Date : May 03, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

Report No.: FG6D2204B

<Radiated Emission> X plane for Part 27L

LF



HF




Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AKJ5-N2 Page Number : C2 of C3
Report Issued Date : May 03, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No.: FG6D2204B

<Radiated Emission> Y plane for Part 22H/24E

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AKJ5-N2 Page Number : C3 of C3
Report Issued Date : May 03, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

Report No. : FG6D2204B