

Report No.: FR771202E


: D1 of D2

Report Issued Date: Aug. 24, 2017

Page Number

Appendix D Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595

Report Version : Rev. 01 Report Template No.: BU5-FR15C Version 2.0 FCC ID: 2AKNO-GW6UL01M2M4





Report No. : FR771202E

<Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: 2AKNO-GW6UL01M2M4 Page Number : D2 of D2
Report Issued Date : Aug. 24, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15C Version 2.0