## **ConnectMe - External photos**



Top side. Transparent to make LED indicator visible. One button interface.



Bottom side. Location of label and fastener. (Label to be updated according to "ConnectMe – Marking label and location information r4.docx")