

PROCESS CONTROL, ROBOTICS, INFORMATION TECHNOLOGY, TELEMETRY

Date: 09.02.2017

AT4 wireless, S.A.U.
Parque Tecnológico de Andalucía
C/ Severo Ochoa 2 & 6
29590 Campanillas
Málaga, España

Ref: Confidentiality request for FCC ID: 2AKQSOKO5875

To whom it may concern:

Pursuant to §0.457(d)(1)(ii) and §0.459 of the Commission's Rules (47 C.F.R.) and §552 (b)(4) of the Freedom of Information Act, Aiut sp. z o.o. (Ltd) hereby request requests that a part of the subject FCC application be held confidential to avoid release of sensitive information of the product to the public.

For the product stated above, we request that the following information be withheld from public disclose:

| Type of Confidentiality Requested | | <u>Exhibit</u> |
|-----------------------------------|-------------|----------------------------|
| ☐ Short Term | □ Permanent | Block Diagrams |
| ☐ Short Term | | External Photos |
| ☐ Short Term | □ Permanent | Internal Photos |
| ☐ Short Term | □ Permanent | Operation Description |
| Short Term | □ Permanent | Parts List & Placement/BOM |
| Short Term | □ Permanent | Tune-Up Procedure |
| Short Term | ⊠ Permanent | Schematics |
| Short Term | | Test Setup Photos |
| ☐ Short Term | | User's Manual |

Permanent confidentiality:

The above materials contain trade secrets and proprietary information not customarily released to the public. The public disclosure of these matters might be harmful to us and provide unjustified benefits to our competitors.

We are also aware that they are responsible to notify AT4 wireless in the event information regarding the product or the product is made available to the public. AT4 wireless will then release the documents listed above for public disclosure pursuant to FCC Public Notice DA 04-1705.

Permanent confidentiality of internal photographs:

The circuit boards of the device are fully encapsulated in epoxy resin. The encapsulant is non-transparent and therefore makes the observation of the circuit boards impossible. The device is designed as irreparable, neither service staff nor users can remove the encapsulant without destroying the device. In the event of technical failure, the device must be replaced with a new one.

Sincerely

Ву:

Grzegorz Szolc

Title:

Certification Engineer

Company:

Aiut sp. z o.o.

Telephone:

+48 607 313 170

e-mail:

grzegorz.szolc@aiut.com.pl



