


RF module





TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018

Report No.: EP882322








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 6 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 7 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018

Report No.: EP882322

Host system





TEL: 886-3-327-3456 FAX: 886-3-327-0973

 Page No.
 : 17 of 46

 EP Report Version
 : Rev. 01

 Issued Date
 : Sep. 26, 2018










SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 18 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 19 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018

Report No.: EP882322









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 20 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 21 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 22 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018

Report No.: EP882322







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 23 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 24 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 25 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 26 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018



otographs of EUT Report No. : EP882322





TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 27 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 28 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 29 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 30 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 31 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 32 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 33 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 34 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 35 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 36 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 37 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018

Report No.: EP882322








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 38 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 39 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 40 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 41 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 42 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 43 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 44 of 46
EP Report Version : Rev. 01
Issued Date : Sep. 26, 2018