
RF module






TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 25

EP Report Version : Rev. 01

Issued Date : Oct. 04, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973

 Page No.
 : 2 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 6 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018






SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 7 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018

Host system






TEL: 886-3-327-3456 FAX: 886-3-327-0973


 Page No.
 : 13 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 14 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973


 Page No.
 : 15 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 16 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 17 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973

 Page No.
 : 18 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973


 Page No.
 : 19 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973

 Page No.
 : 20 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 21 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018








TEL: 886-3-327-3456 FAX: 886-3-327-0973

 Page No.
 : 22 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018





Antenna layout



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 23 of 25
EP Report Version : Rev. 01
Issued Date : Oct. 04, 2018





TEL: 886-3-327-3456 FAX: 886-3-327-0973

 Page No.
 : 24 of 25

 EP Report Version
 : Rev. 01

 Issued Date
 : Oct. 04, 2018