


Prüfbericht - Nr.: 50085890 001

Test Report No.

Seite 1 von 1 Page 1 of 1

Appendix I- Photographs of the Test Set-Up





Photograph 2: Set-up for Radiated Test above 1GHz

