Test report No.
 : 11624584H-B

 Page
 : 46 of 48

 Issued date
 : June 30, 2017

 FCC ID
 : 2AL4MDMS-W1

### **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**




Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 11624584H-B

 Page
 : 47 of 48

 Issued date
 : June 30, 2017

 FCC ID
 : 2AL4MDMS-W1

## **Radiated Spurious Emission**




Photo 1





Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

: 11624584Н-В Test report No. Page : 48 of 48 Issued date : June 30, 2017 FCC ID : 2AL4MDMS-W1

Worst Case Position
(Horizontal: X-axis / Vertical: X-axis)





**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124