

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBB-A11 Page Number : A1 of A4
Report Issued Date : Jun. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC740822



Mode 6





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBB-A11 Page Number : A2 of A4
Report Issued Date : Jun. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBB-A11 Page Number : A3 of A4
Report Issued Date : Jun. 15, 2017
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No. : FC740822

Report No. : FC740822

Mode 6

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBB-A11 Page Number : A4 of A4
Report Issued Date : Jun. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3