


Report No. : FR742716-01A

Setup Photographs

<Conducted Emission>



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBE-0301 Page Number : 1 of 3
Report Issued Date : Aug. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBE-0301 Page Number : 2 of 3
Report Issued Date : Aug. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1



Report No. : FR742716-01A

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBE-0301 Page Number : 3 of 3
Report Issued Date : Aug. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1