

# **Setup Photographs**

# <Conducted Emission>

### Mode 1



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 Page Number : 1 of 3
Report Issued Date : Feb. 07, 2018
Report Version : Rev. 01

Report No.: FR812005A

Report Template No.: BU5-FR15CBT4.0 Version 2.0







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017

Page Number : 2 of 3 Report Issued Date: Feb. 07, 2018

Report Version Report Template No.: BU5-FR15CBT4.0 Version 2.0

: Rev. 01



Report No.: FR812005A


# <Radiated Emission>

## X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 Page Number : 3 of 3
Report Issued Date : Feb. 07, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0