
1. External Photograph of EUT

Model Name: HD34BX


Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 1 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02



Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017


Page Number : 2 of 15 Report Issued Date : Jun. 04, 2018 Report Version : Rev. 02

Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 3 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02

Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 4 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02

Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 5 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02

Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 6 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02