
2. Internal Photograph of EUT

Model Name: HD34BX

Report No.: EP812005




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 7 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02

Report No.: EP812005




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 8 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02

Report No.: EP812005




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 9 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02

Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 10 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02


Report No.: EP812005



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017


Page Number : 11 of 15 Report Issued Date : Jun. 04, 2018 Report Version : Rev. 02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 12 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 13 of 15 Report Issued Date : Jun. 04, 2018 Report Version : Rev. 02



Report No.: EP812005




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017

Page Number : 14 of 15 Report Issued Date : Jun. 04, 2018

Report Version : Rev. 02

Report No.: EP812005



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 IC: 23589-2017 Page Number : 15 of 15
Report Issued Date : Jun. 04, 2018
Report Version : Rev. 02