

Setup Photographs

<Conducted Emission>

Mode 1



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 Page Number : 1 of 3
Report Issued Date : Feb. 07, 2018
Report Version : Rev. 01

Report No.: FR812005B

Report Template No.: BU5-FR15CWL AC MA Version 2.0







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 Page Number : 2 of 3
Report Issued Date : Feb. 07, 2018
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL AC MA Version 2.0




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBG-2017 Page Number : 3 of 3
Report Issued Date : Feb. 07, 2018
Report Version : Rev. 01

Report No.: FR812005B

Report Template No.: BU5-FR15CWL AC MA Version 2.0