## **Setup Photographs**

## <Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 1 of 3
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report No. : FR730732-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 2 of 3
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report No. : FR730732-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3


## <Radiated Emission>

## Y Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 3 of 3
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report No. : FR730732-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3