Shenzhen Fuzhixing Electronics Co., Ltd.

Nov. 25, 2019

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2ALGR-SA70

There are no external tuning adjustments, The amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Fuyuan Zhang Fuyuan Zhang