
3. Internal Photograph of EUT

Brand Name: FSA / Model Name: FD-ED-8400

Report No.: EP760902



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLFDED8400 Page Number : 23 of 27
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Brand Name: FSA / Model Name: FD-ED-8400

Report No.: EP760902




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLFDED8400 Page Number : 24 of 27
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Brand Name: FSA / Model Name: FD-ED-8400


Report No.: EP760902



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLFDED8400 Page Number : 25 of 27
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01


Brand Name: FSA / Model Name: FD-ED-8400

Report No.: EP760902



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLFDED8400 Page Number : 26 of 27
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLFDED8400 Page Number : 27 of 27
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01