1. External Photograph of EUT

Brand Name: FSA / Model Name: SF-ED-8400

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 1 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01



Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 2 of 26 Report Issued Date : Apr. 24, 2018

Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 3 of 26 Report Issued Date : Apr. 24, 2018

Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 4 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 5 of 26 Report Issued Date : Apr. 24, 2018

Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 6 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: FSA / Model Name: SF-ED-8400

Report No.: EP760823

Specification of Accessory		
ADP	Brand Name	FSA
	Model Name	FD019
Battery	Brand Name	FSA
	Model Name	FD017
Cable 1	Brand Name	FSA
	Model Name	FD020
Cable 2	Brand Name	FSA
	Model Name	FD020
Front Derailleur	Brand Name	FSA
	Model Name	FD-ED-8400
Rear Derailleur	Brand Name	FSA
	Model Name	RD-ED-8400

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 7 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 8 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 9 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 10 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 11 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 12 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 13 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 14 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 15 of 26 Report Issued Date : Apr. 24, 2018 Report Version : Rev. 01

Report No.: EP760823



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 16 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01



Front Derailleur

Front Derailleur

Front Derailleur

Brand Name: FSA / Model Name: SF-ED-8400

Front Derailleur

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 17 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823




Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 18 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 19 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01

Report No.: EP760823



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALMLSFED8400 Page Number : 20 of 26
Report Issued Date : Apr. 24, 2018
Report Version : Rev. 01