
Appendix C. Setup Photographs


<Radiated Emission>

X Plane for Part22

LF



HF



SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : C1 of C2
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report No.: FG740704


Report Template No.: BU5-FG22/24 Version 1.2

Y Plane for Part24

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : C2 of C2
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report Template No.: BU5-FG22/24 Version 1.2

Report No. : FG740704