Appendix A. Setup Photographs

<Conducted Emission>

Mode 2





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : A1 of A3
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC740704

Report No. : FC740704

Mode 4





SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : A2 of A3
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 4

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : A3 of A3
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC740704