


## Report No.: FR701703

## Appendix B. Setup Photographs

## <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X

Page Number : B1 of B2 Report Issued Date Nov. 07, 2017 Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0




## FCC RF Test Report

<Radiated Emission>
Y Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA362X Page Number : B2 of B2
Report Issued Date Nov. 07, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR701703