


Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTART400X Page Number : E1 of E2
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01

Report No.: FR852504C


Report Template No.: BU5-FR15EWLB4 AC MA Version 2.0




Report No. : FR852504C

<Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTART400X Page Number : E2 of E2
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 2.0