


Appendix B. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAP50X Page Number : B1 of B2
Report Issued Date Sep. 18, 2017
Report Version : Rev. 01

Report No.: FR781104A

Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAP50X Page Number : B2 of B2
Report Issued Date Sep. 18, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR781104A