
# Appendix A. Setup Photographs

### <Conducted Emission>

#### Mode 4





Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAAN100X


Page Number : A1 of A3 Report Issued Date: Jan. 11, 2018 Report Version : Rev. 01

Report No.: FC7D0401

Report Template No.: BU5-FC15B Version 1.3

### Mode 5





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAAN100X Page Number : A2 of A3
Report Issued Date : Jan. 11, 2018
Report Version : Rev. 01

Report No.: FC7D0401

Report Template No.: BU5-FC15B Version 1.3


## <Radiated Emission>

### Mode 5

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAAN100X Page Number : A3 of A3
Report Issued Date : Jan. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7D0401