

## Appendix B. Setup Photographs

## <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM340X Page Number : B1 of B2
Report Issued Date : Aug. 18, 2017
Report Version : Rev. 01

Report No.: FR770507A


Report Template No.: BU5-FR15CBT Version 2.0




## <Radiated Emission>

## Z plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM340X Page Number : B2 of B2
Report Issued Date : Aug. 18, 2017
Report Version : Rev. 01

Report No.: FR770507A

Report Template No.: BU5-FR15CBT Version 2.0