
Appendix A. Setup Photographs

<Conducted Emission>

Mode 3







TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAPRO550X Page Number : A1 of A3
Report Issued Date : May 31, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC742812



Mode 4






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAPRO550X Page Number : A2 of A3
Report Issued Date : May 31, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

<Radiated Emission>

Mode 4

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAPRO550X Page Number : A3 of A3
Report Issued Date : May 31, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC742812