## Appendix C. Setup Photographs


## <Radiated Emission>

X Plane for LTE Band 2

LF



HF




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : C1 of C3
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No.: FG771706B

## Y Plane for LTE Band 4

LF



HF




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : C2 of C3
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No. : FG771706B

## Z Plane for LTE Band 7

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : C3 of C3
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

Report No. : FG771706B