


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAPRO450X Page Number : B1 of B2
Report Issued Date : May 12, 2017
Report Version : Rev. 01

Report No.: FR731002A

Report Template No.: BU5-FR15CBT Version 1.1




Report No. : FR731002A


<Radiated Emission>

Y Plane

LF



 ${\sf HF}$



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAPRO450X Page Number : B2 of B2
Report Issued Date : May 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1