


Appendix B. Setup Photographs

<Conducted Emission>






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : B1 of B2
Report Issued Date May 22, 2017
Report Version : Rev. 01

Report No.: FR741321A





<Radiated Emission> X Plane LF



 ${\sf HF}$



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : B2 of B2
Report Issued Date May 22, 2017
Report Version : Rev. 01

Report No. : FR741321A