# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589
FAX: +86-755-8637-9595
FCC ID: 2ALTAP50X


Page Number : A1 of A4
Report Issued Date : Sep. 18, 2017
Report Version : Rev. 01

Report No. : FC781104

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC781104

Mode 5





Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAP50X Page Number : A2 of A4
Report Issued Date : Sep. 18, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

## <Radiated Emission>

### Mode 3

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAP50X Page Number : A3 of A4
Report Issued Date : Sep. 18, 2017
Report Version : Rev. 01

Report No. : FC781104

Report Template No.: BU5-FC15B Version 1.3


C Test Report No.: FC781104

#### Mode 5

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAP50X Page Number : A4 of A4
Report Issued Date : Sep. 18, 2017
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3