Appendix A. Setup Photographs

<Conducted Emission>

Mode 4





Sporton International (ShenZhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTA400X Page Number : A1 of A3
Report Issued Date : Aug. 08, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC770404

<Radiated Emission>

Mode 1

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTA400X Page Number : A2 of A3
Report Issued Date : Aug. 08, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC770404


C Test Report No.: FC770404

Mode 4

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTA400X Page Number : A3 of A3
Report Issued Date : Aug. 08, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3