


## Appendix D. Setup Photographs

## <Conducted Emission>





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : D1 of D3
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report No.: FR740704C

Report Template No.: BU5-FR15CWL Version 2.0






## <Radiated Emission>

X Plane

LF



SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : D2 of D3
Report Issued Date : May 16, 2017
Report Version : Rev. 02

Report No.: FR740704C

Report Template No.: BU5-FR15CWL Version 2.0



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM350 Page Number : D3 of D3
Report Issued Date : May 16, 2017
Report Version : Rev. 02
Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR740704C