

## Test Report No. : FR762108

## Appendix B. Setup Photographs

## <Conducted Emission>





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM171X Page Number : B1 of B2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0




## <Radiated Emission>

Z plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM171X Page Number : B2 of B2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report No.: FR762108

Report Template No.: BU5-FR15CBT Version 2.0