


Appendix D. Setup Photographs

<Conducted Emission>





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : D1 of D2
Report Issued Date : May 22, 2017
Report Version : Rev. 01

Report No.: FR741321C






Report No.: FR741321C


<Radiated Emission>

X Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : D2 of D2
Report Issued Date : May 22, 2017
Report Version : Rev. 01