Appendix A. Setup Photographs

<Conducted Emission>

Mode 4





Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : A1 of A3
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01

Report No. : FC771706

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC771706

Mode 5





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: 2ALTAM351X Page Number : A2 of A3
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 5

LF



ΗF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTAM351X Page Number : A3 of A3
Report Issued Date : Aug. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC771706