Appendix A. Setup Photographs

<Conducted Emission>

Mode 1







SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : A1 of A3
Report Issued Date : May 22, 2017
Report Version : Rev. 01

Report No.: FC741321



Mode 4






SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : A2 of A3
Report Issued Date : May 22, 2017
Report Version : Rev. 01


<Radiated Emission>

Mode 4

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM345 Page Number : A3 of A3
Report Issued Date : May 22, 2017
Report Version : Rev. 01

Report No. : FC741321