Appendix D. SAR Test Setup Photos






Report No.: FA871604

Right Cheek



Right Tilted



Left Cheek Left Tilted

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595 Issued Date : Sep. 21, 2018 FCC ID: 2ALTART301X Page D1 of D2 Form version. : 170509







Report No. : FA871604

Front, Test Separation 15 mm

Back, Test Separation 15 mm

Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595 Issued Date : Sep. 21, 2018

FCC ID: 2ALTART301X Page D2 of D2 : 170509 Form version.