


# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 1





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTASC451 Page Number : B1 of B2
Report Issued Date : Aug. 09, 2017
Report Version : Rev. 01

Report No.: FR731002-01A

Report Template No.: BU5-FR15CBT Version 1.1




## Report No.: FR731002-01A


### <Radiated Emission>

Y Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTASC451 Page Number : B2 of B2
Report Issued Date : Aug. 09, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1