

Appendix D. Setup Photographs

<Conducted Emission>





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : D1 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR762205B




<Radiated Emission>

X plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ALTAM355X Page Number : D2 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report No.: FR762205B

Report Template No.: BU5-FR15CBT Version 2.0