



Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA400X Page Number : D1 of D2
Report Issued Date : Aug. 08, 2017
Report Version : Rev. 01

Report No.: FR770404B

Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

X plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2ALTA400X Page Number : D2 of D2
Report Issued Date : Aug. 08, 2017
Report Version : Rev. 01

Report No.: FR770404B

Report Template No.: BU5-FR15CBT Version 2.0